



7 Worcester Road, Barre, MA
800-424-6343

Spring, 2010

Greetings,

It's time for the annual service for your gas appliances, and now is the best time to schedule your appointment. As outlined in your manual, and Mass. Law, your appliances should be inspected and serviced every year.

Please look over the check list attached detailing the maintenance offered. **Our special promotion offer is \$189.00 for the 1st appliance** and any additional appliance would be \$99.00, ***only for appointments scheduled in April, May, June and July.*** After August 1st the price will be \$229.00 with a very limited schedule.

Scheduling service now is a great opportunity to prepare for the long, cold winter ahead, and **also save money!!** Be sure your gas stove runs and operates properly before the heating season starts. A quick test in the off season could prevent a lengthy wait in the fall for service.

Sincerely,

Ron Higgins



7 Worcester Road, Barre, MA
800-424-6343

2010 GAS INSPECTION CHECKLIST *

Valve compartment and firebox top:

- . Vacuum and wipe out dust, cobwebs, debris or pet hair.
- . Verify condition of components in valve compartment. (Confirm the fan is operational.)
- . Confirm all wire connections are not loose or intermittent. Make sure there are no corroded connections.

Logs:

- . Inspect for broken, damaged, or missing logs. Replace as necessary.
- . Verify correct log placement. Verify there is no flame impingement causing sooting. Correct as required.
- . Clean glass and check gaskets

Burner and Flame:

- . Verify the burner is properly secured and aligned with pilot or igniter.
- . Clean off burner top, inspect for plugged ports, corrosion or deterioration.
- . Replace ember materials as needed.
- . Check for smooth lighting and ignition carryover to all ports.
- . Look for lifting or other flame problems.
- . Verify the shutter is clear of dust or debris.
- . Inspect orifice for soot, dirt or corrosion.
- . Verify manifold and inlet pressures.

Pilot or IPI/DSI spark igniter:

- . Inspect pilot flame strength. Clean or replace orifice if required.
- . Inspect thermocouple/thermopile, DSI spark igniter or IPI sensing rod for soot, corrosion and deterioration. Clean or replace as required.
- . Verify millivolt output. Replace if required.

Venting:

- . Inspect for blockage or obstruction such as bird nests, leaves, etc.
- . Confirm that cap remains clear and unobstructed by plants, etc.
- . Verify that termination cap clearance has been maintained.
- . Inspect for corrosion or separation.
- . Inspect condition of draft shield to make sure it is not bent, damaged or lost.

Other:

- . Verify operation of remote.
- . Replace batteries in remote transmitters and battery-powered receivers.
- . Evaluate B-vented models for evidence of back-drafting or negative pressure effects in the house.

SPECIAL PRICING
APRIL 1 - JULY 30

\$189.00*

AFTER
AUGUST 1, 2009

*** Scheduling Limited ***

\$229.00*

~ *ANY PARTS/REPLACEMENT COMPONENTS WILL BE AT AN ADDITIONAL COST.~

~ Payment due in full at time of service ~